

LIFE CYCLE TRACKING PROGRAM
7TH ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
May 31, 2019 @ 11:00 am. 69 degrees and partly cloudy.
2. REAS Application Date, how many years since REAS application
2012 (estimated). 7 Years since REAS Application (believed to be Type II).
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
60
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
70%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
Nothing significant
8. Yes No

X	Color Inconsistent
X	Unevenness in material
X	Cracks
X	Potholes
X	Raveling
9. Any utility or other street cuts, other damage (note specific location)
REAS still holding up well after 7 years with fair color retention. No evidence of raveling. Cracks reflecting through but expected. Normal, relatively uniform wear
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s)
NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO

Evaluated by [REDACTED]
May 31, 2019