

**LIFE CYCLE TRACKING PROGRAM**  
**5<sup>th</sup> ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
5/24/18 @ 4:30 pm. 66 degrees, partly cloudy
2. REAS Application Date, how many years since REAS application  
REAS applied approximately 2013. Approximately 5 years since application
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**  
70 in 2016 and 2017 before re-slurried
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**  
70% in 2016 and 2017 before re-slurried
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
8. **Yes No**

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks (2016 and 2017 before re-slurried)
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Note general or specific problems (include photo name or number and specific location)  
NA
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s))  
NA
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
Yes some segments in 2017, some in 2018. 4-5 years between REAS applications.

**Project File CLOSED**

Evaluated by [REDACTED]  
May 24, 2018