

LIFE CYCLE TRACKING PROGRAM 3rd ANNUAL PHOTOS AND EVALUATION

1. **Date and Time of Report; Note Sky Conditions**
02/18/2019 - 9:30 AM - Sunny
2. **REAS Application Date, how many years since REAS application**
04/17/2016 - 34 months (2.83 Yrs)
3. **Customer and Project Title**
[REDACTED]
4. **Name of street being tracked (include cross street limits)**
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100 - blackest)**
60
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
70%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures if applicable**
Typical transverse and longitudinal reflective cracking.
8. **Yes No**

X		Color Inconsistent
X		Unevenness in Material
X		Cracks
	X	Potholes
X		Raveling (just east of Date Palm Dr. intersection)
9. **Any utility or other street cuts, other damage (note specific location(s) and include photo(s))**
Slight to moderate raveling just east of [REDACTED] cross gutter.
10. **Has street been re-slurry sealed or resurfaced? If so, include photos and close out file**
None observed.
11. **Other Comments**
None.

Evaluated by [REDACTED]
February 18, 2019