

**LIFE CYCLE TRACKING PROGRAM**  
**4th ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
2/21/20, 10:30 am. 76 degrees, partly cloudy.
2. REAS Application Date, how many years since REAS application  
April 17, 2016; almost 4 years since application.
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**  
60
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**  
70%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
8. **Yes No**

X	Color Inconsistent – at times between passes.
X	Unevenness in material
X	Cracks – Transverse and Longitudinal cracks and through some crack seal as well.
X	Potholes
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))  
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
NO
11. Other Comments  
Heavy wear at all intersection edges and around corners. 20-ft long, 3-foot long strip off at [REDACTED] intersection.

Evaluated by [REDACTED]  
February 21, 2020