

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
7/09/20, 1:15 pm. 88 degrees, sunny.
2. REAS Application Date, how many years since REAS application
4/01/19, 1 year after application, Type I.
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**
90
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
95%, only due to some fine cracking.
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
8. **Yes No**

X	Color Inconsistent
X	Unevenness in material
X	Cracks – Some 1/4" wide cracks near 7410, finer cracks various locations.
X	Potholes
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO
11. Other Comments
 - Curb and gutter, no sidewalk.
 - Light wear at Alley entrance across from 7544.

Evaluated by [REDACTED]
July 9, 2020