

**LIFE CYCLE TRACKING PROGRAM**  
**1st ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
7/03/20, 11:30 am. 71 degrees, sunny.
2. REAS Application Date, how many years since REAS application  
7/12/19, 1 year after application, Type I.
3. Customer and Project Title  
██
4. Name of street being tracked (include cross street limits)  
██
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**  
90
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**  
90%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
  - Some wheel path wear starting on E/S near ██████ for 100 feet.
  - Wear at pullout near █████ Street on W/S
8. **Yes No**
  - X Color Inconsistent
  - X Unevenness in material
  - X Cracks – Some light cracking but no crack fill prep was done.
  - X Potholes
  - X Raveling
9. Any utility or other street cuts, other damage (note specific location(s))  
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
NO
11. Other Comments  
None

Evaluated by ██████████  
July 3, 2020